

# Work Order Details

## SP226466: UNIT 3 BOILER BED THERMOCOUPLES ANNUAL OUTAGE (MATS)

UNIT 3 BOILER BED THERMOCOUPLES ANNUAL OUTAGE

**Asset:** **Location:** SP03.BO.IC Unit 03 Boiler Instrumentation **Model:** **Product Version:**

<b>Sched Start:</b>	5/8/2024	<b>Business Unit:</b>	SPUR-Spurlock Station	<b>Job Plan:</b>	INS.064
<b>Sched Finish:</b>		<b>Priority:</b>	3 (Low - Routine)	<b>Supervisor:</b>	
<b>Target Start:</b>	4/17/2024	<b>Work Type:</b>	PM-Preventative Maint	<b>Lead:</b>	
<b>Target Finish:</b>		<b>Status:</b>	WCMP	<b>Vendor:</b>	
<b>Actual Start:</b>	5/7/2024	<b>Parent:</b>		<b>Reported by:</b>	03890
<b>Actual Finish:</b>	5/9/2024	<b>Failure Class:</b>		<b>Reported by:</b>	Kathy Lippert
<b>Report Date:</b>	12/28/2023	<b>Problem Code:</b>		<b>Defect Tag:</b>	NO
<b>Craft:</b>	INS	<b>PM Number:</b>	PM3075	<b>Commodity:</b>	
<b>Unit:</b>	3	<b>GL Account:</b>	512000~SP03~400~3000~03200~BASE~00~00000~00000	<b>Comdty Grp:</b>	
<b>Outage:</b>	Outage	<b>UNID:</b>		<b>Classification:</b>	

Tasks										
WO Task	Task ID	Craft	Description	Status	Sched Start	Sched Finish	Est Hours	Actual Start	Actual Finish	
SP226467	10	OPERATIONS	OPERATIONS LOTO NECESSARY SYSTEMS FOR U3 BOILER BED THERMOCOUPLES INSPECTION AND REPLACEMENT	WCMP	3/9/24	3/9/24	1			
<i>Instructions:</i>										
SP226468	20	INS	UNIT 3 BOILER BED THERMOCOUPLES OUTAGE (MATS)	WCMP	4/24/24	4/25/24	60			
<i>Instructions:</i>										
SP226469	30	OPERATIONS	OPERATIONS REMOVE LOTO NECESSARY SYSTEMS FOR U3 BOILER BED THERMOCOUPLES INSPECTION AND REPLACEMENT	WCMP	3/9/24	3/9/24	1			
<i>Instructions:</i>										

# Work Order Details

## SP226466: UNIT 3 BOILER BED THERMOCOUPLES ANNUAL OUTAGE (MATS)

Planned Labor									
Task ID	Craft	Skill Level	Labor	Vendor	Contract	Qty	Hours	Rate	Line Cost
10	OPERATIONS					1	01:00		
20	INS					2	30:00		
30	OPERATIONS					1	01:00		
	INS					2	05:00		
<b>Total Planned Labor:</b>									

Actual Labor									
Task ID	Craft	Skill Level	Labor	Vendor	Contract Num	Regular Hours	Premium Hours		
	ALL		SP_TL_OT			00:00	00:00		
	INS		03534			00:00	02:00		

Actual Materials									
Task ID	Item Description	Binum	Qty	Unit Cost	Line Cost				
42924	Thermocouple, 38-1/4", 310SS Pipe (W/310SS Barstock Tip)	SWHS3-W3-88-02	4	1503.03	6012.11				
191303004	Gasket, Spiralwound, 316SS, Flexicarb, 2", 150#	SWHSA-FGC-00A-001	4	2.51	10.06				
<b>Total Actual Materials:</b>						6022.16			

Report EK\_woprint.rptdesign