

Work Order

Work Order Code & Desc: DIS - DISCONNECT READOUT

Name: NICHOLAS CONN

Service Id: 20325

Account No: 20326

Route: 09 READ SEQ: 01920

Address: 1124 CONN STREET IVEL

Meter No: W953512

Sequence No: 01920

Comments:

Old Meter Reading: 1890 Old Meter No: W953512 Remote Meter No: _____
New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:

LOCK OFF

Utility Notes: _____ Previous Read: 1881.00000 Date: 06/30/2025
Work Done By: Jimmy Lawson Date Completed: 7-15-25

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

Work Order No: 000000010409

Work Order Code & Desc: DIS - DISCONNECT READOUT

Information Assigned by Office

Name: TONYA GOBLE Phone No: (606)477-1635
 Service Id: 30072 Issue Date: 07/14/2025 09:45
 Account No: 66979 Process Date: 07/14/2025
 Route: 10 READ SEQ 01980 Process Time: 10:00 AM
 Address: 9405 SUITE #2 US HWY 23 STANVILLE Requested By: (606)477-1635
 Meter No: 15C829758 Assigned To: 02 By: VK
 Sequence No: 01980 System:

Comments:

Please lock off and get final reading per customer request. Thank you.

Information From the Field

Old Meter Reading: 4512 Old Meter No: 15C829758 Remote Meter No: _____
 New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:

LOCK OFFUtility Notes: _____ Previous Read: 4512 ~~4220~~0000 Date: 06/30/2025Work Done By: Jimmy Lawson Date Completed: 7-15-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

Work Order No: 000000010414

Work Order Code & Desc: DIS - DISCONNECT READOUT

Information Assigned by Office

Name: CHAD COLLINS Phone No: (606)478-2122
 Service Id: 30310 Issue Date: 07/16/2025 11:31
 Account No: 30310 Process Date: 07/16/2025
 Route: 10 READ SEQ: 02130 Process Time: 12:00 PM
 Address: 31 KY OIL VILLAGE Requested By: Chad (606)478-2122
 Meter No: W953659 Assigned To: 02 By: KBC
 Sequence No: 02130 System:

Comments:

Customer has sold the home, read out an leave on for new customer.

Information From the Field

Old Meter Reading: 3113 Old Meter No: W953659 Remote Meter No: _____
 New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:read outUtility Notes: _____ Previous Read: 3107.00000 Date: 06/30/2025Work Done By: Jimmy Lawson Date Completed: 7-16-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

Work Order Code & Desc: DIS - DISCONNECT READOUT

Name:	<u>RODNEY LAFFERTY</u>	Phone No:	<u>(606)874-0055</u>
Service Id:	<u>40328</u>	Issue Date:	<u>07/16/2025 09:55</u>
Account No:	<u>40328</u>	Process Date:	<u>07/16/2025</u>
Route:	<u>11</u>	Process Time:	<u>10:00 AM</u>
Address:	<u>HOT RODS PIZZA GEORGE RD BETSY</u>	Requested By:	<u>Rodney (606)226-8303</u>
Meter No:	<u>15C829732</u>	Assigned To:	<u>02</u> By: <u>KBC</u>
Sequence No:	<u>02370</u>	System:	

Customer is no longer at this location, read out and lock off.

Information From the Field

Old Meter Reading: 1816 Old Meter No: 15C829732 Remote Meter No: _____

New Meter Reading: _____ New Meter No: _____ Seal No: _____

LOCK OFF

Work Done By: Jimmy Lawson Date Completed: 7-16-25

[illegible]

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

2025

NAVITAS UTILITY CORPORATION

METER CHANGEOUT/PULLED METER FORM

Acct. # 10295 Acct. Name Hunt Robert SYSTEM: Tram
 Route# 8 Sequence# 0801525 Phone# _____
 Service Address: 11 south Lona street DATE: 7-24-25

NEW METER

Meter# 075064199 Temp. Comp. (Y) N
 Meter Make/Size AC 250 Proof Date _____
 # of Dials 4 Pressure: 4 Oz. / PSI
 Pressure factor _____ READING 0

OLD METER/PULLED METER

Meter# W953708
 Meter Make/Size AC 250
 READING ~~1302~~
1314

Appliances on Gas (BTUs)

Hot water heater _____ Tankless water heater _____ Cook stove /
 Central heat / Ventless heater _____ Gas fireplace _____
 Clothes dryer _____ Generator _____ Total BTUs _____

SERVICE CONNECTION CHECKLIST

1. Natural gas odor detected? Y / (N)
2. Appliances/vents free of combustble material? (Y) / N
3. Any alterations from manufactures specifications? Y / (N)
4. Open line found? Y / (N)
5. Proper ventilation in residence? Y / (N)
6. Vent pipes vented above roofs? (Y) / N
7. Was meter lockup checked for 10 minutes? (Y) / N

Service: Turned on: _____ Locked off: _____ Plugged: _____

Home entry denied: Customer signature: _____

Qty.	MATERIALS	Part#
<u>1</u>	<u>meter</u>	

LEAK TEST

Gas Detector: P / F Soap (P) F

Signature: JIMMY

# Hours	EMPLOYEE NAME
<u>1</u>	<u>JIMMY</u>
# Hours	Truck #
<u>1</u>	<u>CHEVY</u>

PIPE CONDITION REPORT

Internal corrosion: Y / (N) Severity: _____
 External corrosion: Y / (N) Severity: _____
 Signature: JIMMY Date: 7/24/2025

1/2/2020

FORM 5

8/28

Work Order

Work Order No: 000000010497

Work Order Code & Desc: DIS - DISCONNECT READOUT

Information Assigned by Office

Name: KRYSTAL LITTERAL
 Service Id: 20093
 Account No: 20099
 Route: 09 READ SEQ: 01710
 Address: 160 CONN ST. SUITE 4 IVEL
 Meter No: 14X478590
 Sequence No: 01710

Phone No: (606)478-3200
 Issue Date: 08/25/2025 08:22
 Process Date: 08/25/2025
 Process Time: 08:30 AM
 Requested By: (606)478-3200
 Assigned To: 02 By: VK
 System:

Comments:

Please read out and lock off on August 28, 2025. Customer is moving. Thank you.

Information From the Field

Old Meter Reading: 3019 Old Meter No: 14X478590 Remote Meter No: _____
 New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:

read out
lock off

Utility Notes: _____ Previous Read: 3019.00000 Date: 08/06/2025

Work Done By: Jimmy Lawson Date Completed: 8-28-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

Work Order Code & Desc: DIS - DISCONNECT READOUT

Information Assigned by Office	
Name: <u>KRYSTAL LITTERAL</u>	Phone No: <u>(606)478-3200</u>
Service Id: <u>20098</u>	Issue Date: <u>08/25/2025 08:23</u>
Account No: <u>20098-2</u>	Process Date: <u>08/25/2025</u>
Route: <u>09</u> READ SEQ: <u>01725</u>	Process Time: <u>08:30 AM</u>
Address: <u>160 CONN STREET IVEL</u>	Requested By: <u>(606)478-3200</u>
Meter No: <u>15C829753</u>	Assigned To: <u>02</u> By: <u>VK</u>
Sequence No: <u>01725</u>	System:
Comments:	

Please read out and lock off on August 28th. Customer is moving. Thank you.	
---	--

Old Meter Reading: 8398 Old Meter No: 15C829753 Remote Meter No: _____
New Meter Reading: _____ New Meter No: _____ Seal No: _____

[illegible]

Utility Notes:	Previous Read:	8398.00000	Date:	08/06/2025
Work Done By:				
Jimmy Lawson	Date Completed:	8-28-25		

8398.00000

Date: 08/06/2025

8-28-25

Charge Summary		
Labor Charges		
Equipment Charges		
Material Charges		
Vendor Charges		
Total		

[illegible]

NAME OF SYSTEM:

Berry Lane

2025


AOC___ LINE PATROL___ 3 YEAR SURVEY___ 5 YEAR SUREVY___

LANDOWNER:_____ PHONE:_____

Date: 8-29-25 Inspector: Jimmy Area Marked: YES___ NO XLocation: Across River From Con StreetAbove Ground: [] Under Ground: [X] Leak Status: Hazardous: X Non-hazardous: ___Nearest Building: 300 ft. Leak Class: 1 Service: Main: XWas Bar Hole Test Performed? Yes___ No XCause of leak: River Shitted. Broke PipeNatural forces(X) Excavation 1st Party: () Excavation 3rd Party: () Outside force: () Mat. or weld: () Equipment: ()

Incorrect operation() Internal Corrosion: () External Corrosion: () Atmospheric Corrosion: () Other: ()

REPAIR REPORT

Type & size of pipe: Steel___ PVC___ PE2"Year pipe installed: 90'sNavitas locate request: Yes___ No XCGI reading in ditch 0

Pipe condition:

External: smooth X badly pitted___ flaking___ deteriorated___ bubble___Internal: smooth X badly pitted___ flaking___ deteriorated___ bubble___Existing pipe info. _____ Photo: Yes___ No XRepair crew: JimmyReport filed by: Jimmy Date: 8-29-25

FORM 1

Temporary Fix until Tim Hull gets here

2025

NAVITAS UTILITY CORPORATION METER CHANGEOUT/PULLED METER FORM

Acct. # 20097 Acct. Name State Beauty Supply SYSTEM: fuel
Route# 09 Sequence# 01705 Phone# 606-478-1818
Service Address: 160 Comm St. Suite #1 DATE: 9/5/2025

NEW METER

Meter# 010179324 Temp. Comp. Y / N
Meter Make/Size AC250 Proof Date _____
of Dials 4 Pressure: 4 Oz. / PSI
Pressure factor _____ READING 0

OLD METER/PULLED METER

Meter# W-953658
Meter Make/Size _____
READING 1985

Appliances on Gas (BTUs)

Hot water heater _____ Tankless water heater _____ Cook stove _____
Central heat ✓ Ventless heater _____ Gas fireplace _____
Clothes dryer _____ Generator _____ Total BTUs _____

SERVICE CONNECTION CHECKLIST

1. Natural gas odor detected? Y / N
2. Appliances/vents free of combustible material? Y / N
3. Any alterations from manufactures specifications? Y / N
4. Open line found? Y / N
5. Proper ventilation in residence? Y / N
6. Vent pipes vented above roofs? Y / N
7. Was meter lockup checked for 10 minutes? Y / N

Service: Turned on: ✓ Locked off: _____ Plugged: _____

Home entry denied: Customer signature: _____

Qty.	MATERIALS	Part#
1	meter	
1	1" valve	

LEAK TEST

Gas Detector: P / F Soap: P / F

Signature: Jimmy

# Hours	EMPLOYEE NAME
1	Jimmy
# Hours	Truck #
1	chev

PIPE CONDITION REPORT

Internal corrosion: Y / N Severity: _____
External corrosion: Y / N Severity: _____
Signature: Jimmy Lawson Date: 9-5-25

1/2/2020

FORM 5

Work Order No: 000000010502

Work Order Code & Desc: REN - RECONNECT SERVICE

Information Assigned by Office

Name: MARILYN RATLIFF Phone No: (606)478-5148
 Service Id: 50320 Issue Date: 09/02/2025 08:24
 Account No: 50320 Process Date: 09/02/2025
 Route: 12 READ SEQ: 02690 Process Time: 08:30 AM
 Address: 1821 MARE CREEK STANVILLE Requested By: Marilyn (606)478-5148
 Meter No: 13N07349 Assigned To: _____ By: TGK
 Sequence No: 02690 System: _____

Comments:

She paid her bill in full and needs the meter turned back on please. Thanks!!

Information From the Field

Old Meter Reading: _____ Old Meter No: 13N07349 Remote Meter No: _____
 New Meter Reading: 573 New Meter No: _____ Seal No: _____

Comments:

unlock mete
Turn on

Utility Notes: 1821 MARE CREEK Previous Read: 573.00000 Date: 08/06/2025
 Work Done By: Jimmy Lawson Date Completed: 9-5-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

2025		Name of System	
NAVITAS UTILITY/ FORT COBB FUEL AUTHORITY JOB INVOICE		Betsy Lane	
START DATE: 9-15-25 FINISH DATE: 9-16-25		NEW CONSTRUCTION Y / N	
LOCATION:		Was this a leak repair? Y / N	
GPS: LAT: LON:		JOB DESCRIPTION	
JOB NAME:		Capped/Plugged Abandoned risers	
QTY. MATERIALS PART#		WAS MAP UPDATED Y / N	
1	3/4" Plug	4127	
1	3/4" CAP	4007	
8	1" Plug	4128	
4	1" CAP	4008	
		JOB PERFORMANCE	
		EMPLOYEE	FUSION GLUE pass/fail
			p / F
			p / F
			p / F
			p / F
		TYPE OF LEAK TEST	
		DATE	DATE
		DATE	DATE
		METHOD	9-15-25 9-16-25
		Gas detector	p / F p / F
		SOAP	p / F p / F
		SIGNATURE	[Signature]
		EFD INFO.	New or Replacement
QTY. PRE-TESTED MATERIALS TEST# PART#			
LABOR & EQUIPMENT HOURS			
Employee, trucks, & equipment.	DATE	DATE	DATE
	DATE	DATE	DATE
Johnny	14	14	
Steven	14	14	
Truck 7	14	14	
Arctic CAT	14	14	
Polaris	14	14	
SIGNATURE: [Signature] DATE: 9-16-25			
1/2/2020 FORM3			



Natural Gas - Leak Data Report - Leak Call / Reported Damage / Maintenance

2025

Section 1 - Required Information Section for any Telephonic Report Received

Taken by: harris Date: 9/29/25 Time: 9:54 AM / PM
Info Source: Call / Work Order / Other, Specify: _____
Person reporting or requesting: Maslene Hall
Community: _____ City: Irrel County: _____
Street: 768 Conn St Address #: _____ Apt #: _____ Zip Code: _____
Phone Number: _____ Cell Phone: 606-478-8728
Nearest Cross Street if no address: _____

Location and description of Leak or Damage at above address: in the hallway and bathroom

Is leak: Inside / Outside / Both { NOTES: In the event of any reported gas leak, instruct the callers to }
Is odor: Strong / Mild / Random / No Odor { evacuate the area to a safe distance immediately - tell them not }
Does any sound accompany smell? Hissing / Whistling / Roaring { to use light switches or take any action that might create a }
How Long have you been smelling the leak or hearing the gas sound? 2 months { spark of any kind and to leave any doors }
{ used to depart (if inside) open. }

Who dispatched? Jimmy Time of Dispatch: 9:57 AM / PM

Work Site Evaluation and Observations by Dispatched Technician

Dispatched Person Arrival Time: 11 AM / PM. Are any AOC's noted? No / Yes: Specify: _____

Is reporting party (if leak or damage call) on the scene? Yes / No

Leak or Damage found: Yes / No If Yes, Navitas side or customer side?
If the leak is on Navitas' side use form 1 to record leak.

Work Conclusion

Dispatched person declares repair complete, site safe and departing @ 1 AM / PM

Actions, Notes, comments or other details of activity on site if needed, including if follow up is needed and the type of follow up:

gas line to ner
heat

Signature of Investigator Jimmy Lawson
Date 9-29-25 Name of System Besty Layne

Work Order

Work Order Code & Desc: DIS - DISCONNECT READOUT

Name:	<u>ARIEL LY</u>	Phone No:	<u>(606)369-5959</u>
Service Id:	<u>20155</u>	Issue Date:	<u>09/26/2025 08:39</u>
Account No:	<u>20154</u>	Process Date:	<u>09/26/2025</u>
Route:	<u>09</u>	Process Time:	<u>09:00 AM</u>
Address:	<u>652 CONN STREET IVEL</u>	Requested By:	<u>(606)369-5959</u>
Meter No:	<u>W953469</u>	Assigned To:	<u>02</u> By: <u>VK</u>
Sequence No:	<u>01775</u>	System:	

Please readout meter 9/30/25 per customer request. Leave on for property owner. Thank you.

Old Meter Reading: 2470 Old Meter No: W953469 Remote Meter No: _____
New Meter Reading: _____ New Meter No: _____ Seal No: _____

leadout meter

Utility Notes: _____ Previous Read: 2459.00000 Date: 09/05/2025
Work Done By: Jimmy Lawson Date Completed: 9-30-25

[illegible]

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

Work Order No: 000000010534

Work Order Code & Desc: DIS - DISCONNECT READOUT

Information Assigned by Office

Name: JANICE JARVIS Phone No: (606)478-8561
 Service Id: 10240 Issue Date: 10/02/2025 07:43
 Account No: 10240 Process Date: 10/02/2025
 Route: 08 READ SEQ: 01495 Process Time: 08:00 AM
 Address: TRAM Requested By: (606)478-8561
 Meter No: W953555 Assigned To: 02 By: VK
 Sequence No: 01495 System:

Comments:

Please readout and lock off, per customer request. Thank you.

Information From the Field

Old Meter Reading: 291 Old Meter No: W953555 Remote Meter No: _____
 New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:Lock offUtility Notes: _____ Previous Read: 291.00000 Date: 09/05/2025Work Done By: Jimmy Lawson Date Completed: 10-2-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

Work Order No: 000000010533

Work Order Code & Desc: REN - RECONNECT SERVICE

Information Assigned by Office

Name: JAMES TACKETT Phone No: (606)205-4759
 Service Id: 30230 Issue Date: 10/02/2025 06:44
 Account No: 30230-1 Process Date: 10/02/2025
 Route: 10 READ SEQ: 02060 Process Time: 07:00 AM
 Address: 42 ALLEN LANE STANVILLE #1 Requested By: (606)616-8138
 Meter No: W953583 Assigned To: 02 By: VK
 Sequence No: 02060 System:

Comments:

Please reconnect service. Customer paid in full plus reconnect fee. Thank you.
 contact # 606-616-8138 or 606-205-4759

Information From the Field

Old Meter Reading: 5695 Old Meter No: W953583 Remote Meter No: _____
 New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:

unlock meter
turn ON

Utility Notes: LOCKED OFF 4/27/22 NON PA Previous Read: 5695.00000 Date: 09/05/2025
 Work Done By: Jimmy Lawson Date Completed: 10-2-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

Work Order

Work Order No: 000000010555

Work Order Code & Desc: RER - RE-READ METER

Information Assigned by Office

Name: JOE'S CAR WASH

Service Id: 30056

Account No: 30056

Route: 10 READ SEQ: 01965

Address: STANVILLE

Meter No: K360690

Sequence No: 01965

Phone No: (606)432-2311
Issue Date: 10/14/2025 13:33
Process Date: 10/14/2025
Process Time: 02:00 PM
Requested By: (606)432-2311
Assigned To: 02 By: VK
System:

Comments:

Please get current reading and leave on for new owner. Thank you.

Information From the Field

Old Meter Reading: 8150 Old Meter No: K360690 Remote Meter No: _____
New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:

Read out

Utility Notes: _____ Previous Read: 8170.00000 Date: 10/06/2025
Work Done By: Jimmy Lawson Date Completed: 10-14-25

Work Done By: Timmy Lawson

Date Completed: 10-19-23

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

[illegible]

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

Work Order No: 000000010535

Work Order Code & Desc: DIS - DISCONNECT READOUT

Information Assigned by Office

Name: WHITLEY HALL
 Service Id: 30060
 Account No: 30060AA
 Route: 10 READ SEQ: 01970
 Address: 9248 HWY 23 SOUTH STANVILLE
 Meter No: W953534
 Sequence No: 01970

Phone No: (859)421-7187
 Issue Date: 10/03/2025 07:10
 Process Date: 10/03/2025
 Process Time: 07:30 AM
 Requested By: (859)421-7187
 Assigned To: 02 By: VK
 System:

Comments:

Please readout ~~XXXXXXXXXX~~ 10-6-2025. Customer has sold property. Thank you.

Information From the Field

Old Meter Reading: 2268 Old Meter No: W953534 Remote Meter No: _____
 New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:

Reads Read out

Utility Notes: _____ Previous Read: 2264.00000 Date: 09/05/2025

Work Done By: Jimmy Lawson Date Completed: 10-15-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

Work Order No: 000000010556

Work Order Code & Desc: RER - RE-READ METER

Information Assigned by Office

Name: LARRY PETSCH Phone No: (606)424-1907
 Service Id: 10095 Issue Date: 10/15/2025 10:23
 Account No: 10095 Process Date: 10/15/2025
 Route: 08 READ SEQ: 01465 Process Time: 10:30 AM
 Address: 72 RIVERBEND DRIVE TRAM Requested By: Larry (606)424-1907
 Meter No: W953600 Assigned To: _____ By: TGK
 Sequence No: 01465 System: _____

Comments:

Can you re-read this meter please? His usage went from 7ccf to 97 ccfs. Thanks!!

Information From the Field

Old Meter Reading: 3425 Old Meter No: W953600 Remote Meter No: _____
 New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:

~~re-read~~ re-read meter

Utility Notes: _____ Previous Read: 3414.00000 Date: 10/06/2025

Work Done By: Jimmy Lawson Date Completed: 10-15-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

Work Order No: 000000010564

Work Order Code & Desc: DIS - DISCONNECT READOUT

Information Assigned by Office

Name: _____ Phone No: _____
 Service Id: 40010 Issue Date: 10/17/2025 08:26
 Account No: _____ Process Date: 10/17/2025
 Route: 11 READ SEQ: 02211 Process Time: 08:30 AM
 Address: 42 FOUNTAIN LANE BETSY LAYNE Requested By: _____
 Meter No: 15C829745 Assigned To: 02 By: VK
 Sequence No: 02211 System: _____

Comments:

Please pull meter and risor, cap line as requested by Brett Meade

Information From the Field

Old Meter Reading: 3839 Old Meter No: 15C829745 Remote Meter No: _____
 New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:pull meter and risor
cap line

Utility Notes: _____ Previous Read: 3839.00000 Date: 09/06/2023
 Work Done By: _____ Date Completed: _____

Labor Charges			
Name	Rate	Hours	Amount
Jimmy		5	
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
4008	1" cap	1		
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	


Work Order Code & Desc: RER - RE-READ METER

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

[illegible]

North

2025



BAR-HOLE DIAGRAM

Each circular line is equal to two feet.

NAME OF INSPECTOR: Johnny Type of instrument: SensitGold G2
DATE: 9-15-25 Serial #: G264769
LOCATION: 664 Mare Rd. Creek Rd
NAME OF LAND OWNER: 610

Form 7
1/2/2020

NAME OF SYSTEM:

Betsy Lane

2025

AOC___ LINE PATROL___ 3 YEAR SURVEY___ 5 YEAR SUREVY X

LANDOWNER:_____ PHONE:_____

Date: 9-15-25 ^{OP} Inspector: Johnny Area Marked: YES X NO___Location: 664 Mare ~~Creel~~ RdAbove Ground: [] Under Ground: [X] Leak Status: Hazardous:___ Non-hazardous: XNearest Building: 150 ft. Leak Class: 3 Service: X Main:___Was Bar Hole Test Performed? Yes X No___Cause of leak: Riser Had 2 VALVES. Bottom Valve WAS Turned onNatural forces() Excavation 1st Party: () Excavation 3rd Party: () Outside force: (X) Mat. or weld: () Equipment: ()

Incorrect operation() Internal Corrosion: () External Corrosion: () Atmospheric Corrosion: () Other: ()


REPAIR REPORT

Type & size of pipe: Steel 1" PVC___ PE___

Year pipe installed: _____

Navitas locate request: Yes___ No X

CGI reading in ditch _____



Pipe condition:

External: smooth X badly pitted___ flaking___ deteriorated___ bubble /Internal: smooth X badly pitted___ flaking___ deteriorated___ bubble /

Existing pipe info. _____ Photo: Yes___ No___

Repair crew: Jimmy LawsonReport filed by: Jimmy Lawson Date: 10/20/25

FORM 1

1" Cap Line

Riser Had 2 VALVES on it. The 1ST VALVE WAS Turned on underground.
Turned VALVE off, Took Riser Apart to that VALVE AND Capped.

NUC Contact:

NAVITAS UTILITY CORPORATION

2025

Date:

SERVICE CHECK

NEW SERVICE / RECONNECT / RELIGHT

Phone # 606-478-1989

Acct. # 40190

Acct. Name George Bell Jr.

SYSTEM: Betaytane

Service I.D.# 40190

Route# 11

Sequence# 02345

Service Address: 199 Stone Hollow Rd.

DATE: 10/22/2025

911 Address: same

METER INFORMATION

Meter# W953615

Pressure setting: 4 Oz. / PSI

Proof date _____

Meter Make/Size AC 250

Pressure factor _____

READING 3569

Number of Dials 4

Temp. Comp. (Y) N

SERVICE CONNECTION CHECKLIST

Natural gas odor detected? (Y) N

Appliances/vents free of combustible material? (Y) N

Any alterations from manufactures specifications? (Y) N

Open line found? (Y) N

Proper ventilation in residence? (Y) N

Vent pipes vented above roofs? (Y) N

Was meter lockup performed for 10 Minutes? (Y) N

PIPE CONDITION REPORT

INTERNAL: Y / N

SEVERITY: _____

EXTERNAL: Y / N

SEVERITY: _____

NAME: _____

DATE: _____

Appliances on Gas (BTUs)

Hot water heater _____

Tankless water heater _____

Cook stove _____

Central heat _____

Ventless heater _____

Gas fireplace _____

Clothes dryer _____

Generator _____

Total BTUs _____

Customer service line responsibility sheet: Customer Initials: _____

Service: Turned on: / Locked off: _____ Plugged: _____

Home entry denied: Customer signature: _____

SERVICEMAN SIGNATURE: Jimmy Lawson DATE of completion: 10-22-25

CUSTOMER SIGNATURE: _____ DATE: _____

COMPLETE FOR NEW CONSTRUCTION & SERVICES NOT USED FOR TWO YEARS OR LONGER.

Was a pressure test run for 4 hours at a minimum of 10 PSIG? Signature: _____

Does this qualify for new customer bonus? Y N

Approved by: _____ Date: _____

FORM 6

1/8/2025

Work Order No:

Work Order Code & Desc: -

Information Assigned by Office

Name: Emil Maynor
 Service Id: 30054
 Account No: _____
 Route: 10 READ SEQ: 01960
 Address: 30 E Main Behind Joe's Car Wash
 Meter No: W95.3610
 Sequence No: 30054

Phone No: _____
 Issue Date: 10/22/2005
 Process Date: _____
 Process Time: _____
 Requested By: _____
 Assigned To: Jimmy By: Valarie
 System: KY

Comments:

Please Lock off meter - New owners are not going to use gas. Thank you!

Information From the Field

Old Meter Reading: 2770 Old Meter No: _____ Remote Meter No: _____
 New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:

LOCK OFF

Utility Notes: _____

Previous Read: _____ Date: _____

Work Done By: Jimmy LawsonDate Completed: 10-22-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

Work Order No: 000000010592

Work Order Code & Desc: REN - RECONNECT SERVICE

Information Assigned by Office

Name: CARL MEADE Phone No: (606)339-4414
 Service Id: 30102 Issue Date: 10/29/2025 07:23
 Account No: 30101 Process Date: 10/29/2025
 Route: 10 READ SEQ: 01995 Process Time: 07:30 AM
 Address: 132 EAST MAIN ST STANVILLE Requested By: (606)339-4414
 Meter No: W953626 Assigned To: 02 By: KBC
 Sequence No: 01995 System:

Comments:

Customer has paid in full plus a reconnect. Someone will be there for you to turn back on.

Information From the Field

Old Meter Reading: 5510 Old Meter No: W953626 Remote Meter No: _____
 New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:

meter unlock
turn on

Utility Notes: SERVICE ON 11/17/2023 Previous Read: 5510.00000 Date: 10/06/2025Work Done By: Simmy Lawson Date Completed: 10-29-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

NUC Contact:

NAVITAS UTILITY CORPORATION

2025

Date:

SERVICE CHECK
NEW SERVICE / RECONNECT / RELIGHT

Phone # 606-791-0744

Acct. # 2089 Acct. Name E. Ky Vendor Mail Kentucky SYSTEM: KY
Service I.D.# 20098 Route# 9 Sequence# 01725
Service Address: 160 Conn St. Ivel DATE: 10/30/25
911 Address: 160 Conn St. Ivel

METER INFORMATION

Meter# 15C829753 Pressure setting: 4 Oz. / PSI Proof date 17
Meter Make/Size AC 250 Pressure factor _____ READING 8398
Number of Dials 4 Temp. Comp. (Y) / N

SERVICE CONNECTION CHECKLIST

Natural gas odor detected? (Y) / N
Appliances/vents free of combustible material? (Y) / N
Any alterations from manufactures specifications? Y / N
Open line found? Y / (N)
Proper ventilation in residence? Y / N
Vent pipes vented above roofs? (Y) / N
Was meter lockup performed for 10 Minutes? (Y) / N

PIPE CONDITION REPORT

INTERNAL: Y / N
SEVERITY: _____
EXTERNAL: Y / N
SEVERITY: _____
NAME: _____
DATE: _____

Appliances on Gas (BTUs)

Hot water heater _____ Tankless water heater _____ Cook stove _____
Central heat _____ Ventless heater _____ Gas fireplace _____
Clothes dryer _____ Generator _____ Total BTUs _____

Customer service line responsibility sheet: Customer Initials: _____

Service: Turned on: / Locked off: _____ Plugged: _____

Home entry denied: Customer signature: _____

SERVICEMAN SIGNATURE: Jimmy Lawson DATE of completion: 10-30-25

CUSTOMER SIGNATURE: _____ DATE: _____

COMPLETE FOR NEW CONSTRUCTION & SERVICES NOT USED FOR TWO YEARS OR LONGER.

Was a pressure test run for 4 hours at a minimum of 10 PSIG? Signature: _____

Does this qualify for new customer bonus? Y N

Approved by: _____ Date: _____

FORM 6

1/8/2025

Work Order No: 000000010599

Work Order Code & Desc: CKP - CHECK GAS PRESSURE

Information Assigned by Office

Name: MICHAEL PRESTON Phone No: (606)478-1868
 Service Id: 30267 Issue Date: 10/30/2025 07:38
 Account No: 30267 Process Date: 10/30/2025
 Route: 10 READ SEQ: 02085 Process Time: 08:00 AM
 Address: 238 BOBCAT BLVD STANVILLE Requested By: Michael (606)478-1868
 Meter No: 15C829749 Assigned To: _____ By: TGK
 Sequence No: 02085 System: _____

Comments:

He needs someone to check the pressure at the meter please. his number is 606-477-3291
 Thanks

Information From the Field

Old Meter Reading: _____ Old Meter No: 15C829749 Remote Meter No: _____
 New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:

gas pressure is ~~now~~ good
 402

Utility Notes: _____ Previous Read: 2460.00000 Date: 10/06/2025

Work Done By: Jimmy Lawson Date Completed: 10-30-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

Work Order No: 000000010604

Work Order Code & Desc: REN - RECONNECT SERVICE

Information Assigned by Office

Name: TONYA GOBLE Phone No: (606)477-1635
 Service Id: 30072 Issue Date: 11/03/2025 11:46
 Account No: 66979 Process Date: 11/03/2025
 Route: 10 READ SEQ: 01980 Process Time: 12:00 PM
 Address: 9405 SUITE #2 US HWY 23 STANVILLE Requested By: Tonya (606)477-1635
 Meter No: 15C829758 Assigned To: 02 By: TGK
 Sequence No: 01980 System:

Comments:

They are wanting that meter turned back on now. Just when you have time. Thanks

Information From the Field

Old Meter Reading: 4512 Old Meter No: 15C829758 Remote Meter No: _____
 New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:

unlock meter

Utility Notes: _____ Previous Read: 4512.00000 Date: 07/15/2025

Work Done By: Simmy Lawson Date Completed: 11-4-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

Work Order No: 000000010620

Work Order Code & Desc: REN - CHECK GAS PRESSURE

Information Assigned by Office

Name: SHANE JUSTICE
 Service Id: 50171
 Account No: 50171
 Route: 12 READ SEQ: 02545
 Address: 85 SHOP BRANCH MARE CREEK
 Meter No: L994253
 Sequence No: 02545

Phone No: (606)478-5185
 Issue Date: 11/10/2025 11:06
 Process Date: 11/10/2025
 Process Time: 11:30 AM
 Requested By: Marsha (606)371-2677
 Assigned To: _____ By: TGK
 System: _____

Comments:

Hey, can you check their meter and make sure it is working please? They can't get their fireplaces to light.
 I told her it would be tomorrow before you could check it.

Information From the Field

Old Meter Reading: _____ Old Meter No: L994253 Remote Meter No: _____
 New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:

gas is ~~off~~ OK to ~~Home~~ Home

Utility Notes: LOCKED OFF 5-31-22 NON PAPrevious Read: 3315.00000 Date: 11/06/2025Work Done By: Jimmy LawsonDate Completed: 11-11-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

Work Order Code & Desc: REN - RECONNECT SERVICE

Work Done By: Jimmy Lawson Date Completed: 11-11-25

Work Order No: 000000010623

Work Order Code & Desc: REN - RECONNECT SERVICE

Information Assigned by Office

Name: DESTA LEE
 Service Id: 10336
 Account No: 10336
 Route: 08 READ SEQ 01545
 Address: 67 LEE STREET TRAM
 Meter No: W953637
 Sequence No: 01545

Phone No: (606)331-0901
 Issue Date: 11/13/2025 06:50
 Process Date: 11/13/2025
 Process Time: 07:00 AM
 Requested By: (606)331-0901
 Assigned To: 02 By: VK
 System:

Comments:

Please reconnect service. Thank you.

Information From the Field

Old Meter Reading: 8819 Old Meter No: W953637 Remote Meter No: _____
 New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:

unlock meter
turn on

Utility Notes: _____ Previous Read: 8819.00000 Date: 07/11/2025

Work Done By: Jimmy Lawson Date Completed: 11-13-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

NUC Contact:

Date:

NAVITAS UTILITY CORPORATION

SERVICE CHECK

NEW SERVICE / RECONNECT / RELIGHT

2025

Phone # 606-454-8469

Acct. #

20324

Acct. Name

Jacob Mullens

SYSTEM:

Irrel

Service I.D.#

20325

Route#

09

Sequence#

01920

Service Address:

1124 Lonn St

DATE:

11/18/2025

911 Address:

same

METER INFORMATION

Meter#

W953512

Pressure setting:

4

Oz. / PSI

Proof date

Meter Make/Size

AC-25

Pressure factor

Number of Dials

4

Temp. Comp.

Y / N

READING

1890

SERVICE CONNECTION CHECKLIST

Natural gas odor detected?

Y / N

Appliances/vents free of combustible material?

Y / N

Any alterations from manufactures specifications?

Y / N

Open line found?

Y / N

Proper ventilation in residence?

Y / N

Vent pipes vented above roofs?

Y / N

Was meter lockup performed for 10 Minutes?

Y / N

PIPE CONDITION REPORT

INTERNAL: Y / N

SEVERITY:

EXTERNAL: Y / N

SEVERITY:

NAME:

DATE:

Appliances on Gas (BTUs)

Hot water heater

Tankless water heater

Cook stove

Central heat

Ventless heater

Gas fireplace

Clothes dryer

Generator

Total BTUs

Customer service line responsibility sheet: Customer Initials:

Service: Turned on: / Locked off: Plugged:

Home entry denied: Customer signature:

SERVICEMAN SIGNATURE:

Jimmy Lawson

DATE of completion:

11-18-25

CUSTOMER SIGNATURE:

DATE:

COMPLETE FOR NEW CONSTRUCTION & SERVICES NOT USED FOR TWO YEARS OR LONGER.

Was a pressure test run for 4 hours at a minimum of 10 PSIG? Signature:

FORM 6

1/2/2020

Work Order No: 000000010646

Work Order Code & Desc: DIS - DISCONNECT READOUT

Information Assigned by Office

Name: DANIEL ALLEN Phone No: (606)939-2743
 Service Id: 50140 Issue Date: 11/21/2025 13:32
 Account No: 501402 Process Date: 11/21/2025
 Route: 12 READ SEQ: 02485 Process Time: 02:00 PM
 Address: 1014 MARE CREEK STANVILLE Requested By: Daniel (606)939-2743
 Meter No: W953478 Assigned To: 02 By: KBC
 Sequence No: 02485 System:

Comments:

Customer has sold the property, read out and lock off.

Information From the Field

Old Meter Reading: 4999 Old Meter No: W953478 Remote Meter No: _____
 New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:Lock off

Utility Notes:

Previous Read:

4995.00000Date: 11/06/2025

Work Done By:

Jimmy Lawson

Date Completed:

11-21-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	



Natural Gas -- Leak Data Report / Leak Call / Reported Damage / Maintenance

2025

Section 1 -- Required Information Section for any Telephonic Report Received

Taken by: Tronda Date: 12/3/25 Time: 8:50 AM/PM
 Info Source: Call/Work Order/Other- Specify: Call
 Person reporting or requesting: Andrea Collins for John Hunt
 Community: Stanville City: Stanville County: Floyd
 Street: 37 Shop Branch Address #: 37 Apt #: Zip Code: 41659
 Phone Number Cell Phone 606-791-2218
 Nearest Cross Street if no address:
 Location and description of Leak or Damage at above address: Smelling gas in the house

Is leak: Inside / Outside / Both { NOTES: In the event of any reported gas leak, instruct the callers to }
 Is odor: Strong / Mild / Random / No Odor { evacuate the area to a safe distance immediately -- tell them not }
 Does any sound accompany smell? Hissing / Whistling / Roaring (to use light switches or take any action that might create a)
 How Long have you been smelling the leak or hearing the gas sound? 2 days { spark of any kind and to leave any doors }
 { used to depart (if inside) open. }
 Who dispatched? Jimmy Lawson Time of Dispatch: 8:53 AM/PM

Work Site Evaluation and Observations by Dispatched Technician

Dispatched Person Arrival Time: 9:30 AM/ PM. Are any AOC's noted? No Yes: Specify:
 Is reporting party (if leak or damage call) on the scene? Yes / No
 Leak or Damage found: Yes / No If Yes, Navitas side or customer side?
 If the leak is on Navitas' side use form 1 to record leak.

Work Conclusion

Dispatched person declares repair complete, site safe and departing @ 10:35 AM/ PM
 Actions, Notes, comments or other details of activity on site if needed, including if follow up is needed and the type of follow up:
Found LEAK ON Stove. Customer will Replace line & Stove. Turn
VALVE OFF TO Stove.

Signature of Investigator Jimmy Lawson
 Date 12/3/25 Name of System Betsy Lane

Work Order No: 000000010098

Work Order Code & Desc: CKP - CHECK GAS PRESSURE

Information Assigned by Office

Name: NATHAN COLEMAN Phone No: (606)210-0187
Service Id: 011090 Issue Date: 01/08/2025 11:54
Account No: 11090 Process Date: 01/08/2025
Route: 35 READ SEQ00550 Process Time: 12:00 PM
Address: 198 MULLINS ADDITION DR Requested By: Nathan (606)210-0187
Meter No: 13773940 Assigned To: _____ By: TGK
Sequence No: 00550 System: _____

Comments:

Customer may be having pressure problems with the colder temps. Her number is 606-831-5989.

Information From the Field

Old Meter Reading: _____ Old Meter No: 13773940 Remote Meter No: _____
New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:

Ice had fell from roof and shut valve almost completely off. Turned Valve back on, had good pressure.

Utility Notes: _____ Previous Read: 7216.00000 Date: 01/06/2025
Work Done By: Nathan Coleman Date Completed: 1-8-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

Work Order No: 000000010103

Work Order Code & Desc: CKP - CHECK GAS PRESSURE

Information Assigned by Office

Name: JUDY LOONEY Phone No: (606)205-1033
 Service Id: 011060 Issue Date: 01/14/2025 09:58
 Account No: 11060 Process Date: 01/14/2025
 Route: 35 READ SEQ: 00400 Process Time: 10:00 AM
 Address: 145 MULLINS ADDITION DR Requested By: Judy (606)205-1033
 Meter No: 1501499 Assigned To: _____ By: KBC
 Sequence No: 00400 System: _____

Comments:

Customer has no gas, please check to see if it is froze off or what is wrong.

Thanks

Information From the Field

Old Meter Reading: _____ Old Meter No: 1501499 Remote Meter No: _____
 New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:

Gas was on upon arrival. Cust had been gone for a few days
 and said her house ~~was~~ seemed cold. Furnace & water heater were working

Utility Notes: _____ Previous Read: 2955.00000 Date: 01/06/2025

Work Done By: Patricia Mahle Date Completed: 1-14-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

Work Order No: 000000010098

Work Order Code & Desc: CKP - CHECK GAS PRESSURE

Information Assigned by Office

Name: NATHAN COLEMAN Phone No: (606)210-0187
 Service Id: 011090 Issue Date: 01/08/2025 11:54
 Account No: 11090 Process Date: 01/08/2025
 Route: 35 READ SEQ00550 Process Time: 12:00 PM
 Address: 198 MULLINS ADDITION DR Requested By: Nathan (606)210-0187
 Meter No: 13773940 Assigned To: _____ By: TGK
 Sequence No: 00550 System: _____

Comments:

Customer may be having pressure problems with the colder temps. Her number is 606-831-5989.

Information From the Field

Old Meter Reading: _____ Old Meter No: 13773940 Remote Meter No: _____
 New Meter Reading: _____ New Meter No: _____ Seal No: _____

Comments:

Ice had fell from roof and shut valve almost completely off. Turned Valve back on, had good pressure.

Utility Notes: _____ Previous Read: 7216.00000 Date: 01/06/2025

Work Done By: Nathan Coleman Date Completed: 1-8-25

Labor Charges			
Name	Rate	Hours	Amount
Total Labor Charges			

Equipment Charges			
Name	Rate	Hours	Amount
Total Equipment Charges			

Material Charges				
Part #	Item	Qty.	Unit Price	Total
Total Material Charges				

Outside Vendor Charges			
Name	PO Number	Job Date	Amount
Total Vendor Charges			

Charge Summary	
Labor Charges	
Equipment Charges	
Material Charges	
Vendor Charges	
Total	

[illegible]

PIPELINE FIELD TEST REPORT 2024

NAVITAS UTILITY CORP.

SYSTEM: Navitas Utility

This form must be completed for each section of newly installed section of main or service line.

TEST DATA

Location of line: Happy Hollow Van Lear KY

Pipe information: HDPE SDR 11- tested roll @ 60 psig for 1 hour.

Size of pipe: 1 inches. Length of line: 500 ft. Main ☒ Service ()

Pipe information: HDPE SDR 11- tested roll @ 60 psig for 1 hour.

Size of pipe: 1 inches. Length of line: 85 ft. Main () Service ☒

Pipe information: HDPE SDR 11- Tested @ 60 psig for 1 hour. Installed Lyco EFVI Series 475.

Size of pipe: _____ inches. Length of line: _____ Main () Service ()

Pipe information: _____

Size of pipe: _____ inches. Length of line: _____ Main () Service ()

Tested with: Air ☒ Natural Gas () Gauge #: 69411

Time started: 9:07 a.m./p.m. Time ended: 10:07 a.m./p.m.

Test pressure start: 60 psig

Test pressure stop: 60 psig

Line loss: Yes () No ☒

Remarks: _____

Signature: Ruth Hable Date: 4-22-24

2024

NUC / FCFA PIPELINE UPDATE WORK SHEET

SYSTEM: Navitas Utility DATE: 4-22-24
 LOCATION: Happy Hollow Van Lear KY
 GPS COORDINATES: LAT: 37.7764457 LON: -82.7654436
 Map update (Yes) or No)

() PIPELINE RETIREMENT

MAIN () SERVICE ()

TYPE OF PIPE: _____

SIZE OF PIPE: _____

LENGTH OF LINE: _____

REASON FOR RETIREMENT: _____

WAS LINE PURGED WITH AIR? Y / N % NG _____

(✓) NEW PIPELINE INSTALLATION

MAIN (✓) SERVICE ()

TYPE OF PIPE: HDPE SDR 11SIZE OF PIPE: 1"LENGTH OF LINE: 500 ft.

CUSTOMER NAME IF SERVICE LINE: _____

WAS LINE PURGED WITH NATURAL GAS? (Y) / N % NG 100() PIPELINE REPLACEMENT

MAIN () SERVICE ()

TYPE OF EXISTING PIPE: _____

SIZE OF EXISTING PIPE: _____

TYPE OF NEW PIPE: _____

SIZE OF NEW PIPE: _____

LENGTH OF LINE BEING REPLACED: _____

WAS OLD LINE PURGED WITH AIR? Y / N % NG _____

WAS NEW LINE PURGED WITH NATURAL GAS? Y / N % NG _____

PIPE CONDITION REPORT

INTERNAL CORROSION: Y / N SEVERITY: _____

EXTERNAL CORROSION: Y / N SEVERITY: _____

SIGNATURE: Nathan Koble

1/2/2020

DATE: 4-22-24

FORM 4

NUC / FCFA PIPELINE UPDATE WORK SHEET

2024

SYSTEM: Navitas Utility DATE: 4-22-24
 LOCATION: Happy Hollow Van Lear KY
 GPS COORDINATES: LAT: 37.7774397 LON: -82.7646952
 Map update (Yes or No)

() PIPELINE RETIREMENT MAIN () SERVICE ()

TYPE OF PIPE: _____

SIZE OF PIPE: _____

LENGTH OF LINE: _____

REASON FOR RETIREMENT: _____

WAS LINE PURGED WITH AIR? Y / N % NG _____

(☒) NEW PIPELINE INSTALLATION MAIN () SERVICE (☒)

TYPE OF PIPE: HDPE SDR 11

SIZE OF PIPE: 1"

LENGTH OF LINE: 85 ft.

CUSTOMER NAME IF SERVICE LINE: Josh Barker

WAS LINE PURGED WITH NATURAL GAS? ☒ Y / N % NG 100

() PIPELINE REPLACEMENT MAIN () SERVICE ()

TYPE OF EXISTING PIPE: _____

SIZE OF EXISTING PIPE: _____

TYPE OF NEW PIPE: _____

SIZE OF NEW PIPE: _____

LENGTH OF LINE BEING REPLACED: _____

WAS OLD LINE PURGED WITH AIR? Y / N % NG _____

WAS NEW LINE PURGED WITH NATURAL GAS? Y / N % NG _____

PIPE CONDITION REPORT

INTERNAL CORROSION: Y / N SEVERITY: _____

EXTERNAL CORROSION: Y / N SEVERITY: _____

SIGNATURE: Nathan Seale

1/2/2020

DATE: 4-22-24

FORM 4

NAVITAS UTILITY CORPORATION 2024
RISER PRESSURE TEST

Riser number 0001 Pipe size 1" Location of test Field

Riser information: 1" IPS Central Plastics anodless riser

Gauge number 69411 Test with Air Start time 2:07pm End time 3:07pm Temp. _____

Start pressure 60psig End pressure 60psig Date 4-22-24 Signature Pattho Goble

Location set 99 Happy Hollow behind house

Date set 4-22-24 Signature Pattho Goble

Riser number _____ Pipe size _____ Location of test _____

Riser information: _____

Gauge number _____ Test with _____ Start time _____ End time _____ Temp. _____

Start pressure _____ End pressure _____ Date _____ Signature _____

Location set _____

Date set _____ Signature _____

Riser number _____ Pipe size _____ Location of test _____

Riser information: _____

Gauge number _____ Test with _____ Start time _____ End time _____ Temp. _____

Start pressure _____ End pressure _____ Date _____ Signature _____

Location set _____

Date set _____ Signature _____

NAVITAS UTILITY CORPORATION 2024
EFV PRESSURE TEST

EFV number 525 Pipe size 1" Location of test Field

EFV information: HDPE LYCO EFV 1 Series 475

Gauge number 69411 Test with Air Start time 9:07 End time 9:10 Temp. _____

Start pressure 5psig End pressure 5psig Date 4-22-24 Signature Nathn Sahle

Location set 99 Happy Hollow Rd. @ Tap

Date set 4-22-24 Signature Nathn Sahle

EFV number _____ Pipe size _____ Location of test _____

EFV information: _____

Gauge number _____ Test with _____ Start time _____ End time _____ Temp. _____

Start pressure _____ End pressure _____ Date _____ Signature _____

Location set _____

Date set _____ Signature _____

EFV number _____ Pipe size _____ Location of test _____

EFV information: _____

Gauge number _____ Test with _____ Start time _____ End time _____ Temp. _____

Start pressure _____ End pressure _____ Date _____ Signature _____

Location set _____

Date set _____ Signature _____

[illegible]

PIPELINE FIELD TEST REPORT 2024

NAVITAS UTILITY CORP.

SYSTEM: Navitas Utility

This form must be completed for each section of newly installed section of main or service line.

TEST DATA

Location of line: Rt. 1100 East Point KY

Pipe information: HDPE SDR 11 - Tested roll @ 60 psig for 1
hour.

Size of pipe: 1 inches. Length of line: 500 ft. Main () Service (X)

Pipe information: HDPE SDR 11 - Tested roll @ 60 psig for 1
hour

Size of pipe: 1 inches. Length of line: 500 ft. Main () Service (X)

Pipe information: _____

Size of pipe: _____ inches. Length of line: _____ Main () Service ()

Pipe information: _____

Size of pipe: _____ inches. Length of line: _____ Main () Service ()

Tested with: Air (✓) Natural Gas () Gauge #: 69411

Time started: 8:45 (a.m./p.m.) Time ended: 9:45 (a.m./p.m.)

Test pressure start: 60 psig

Test pressure stop: 60 psig

Line loss: Yes () No (X)

Remarks: _____

Signature: Ruth Gable Date: 4-23-24

NUC / FCFA PIPELINE UPDATE WORK SHEET

2024

SYSTEM: Navitas Utility DATE: 4-23-24
 LOCATION: Rt. 1100 East Point KY
 GPS COORDINATES: LAT: 37.7278618 LON: -82.7835066
 Map update (Yes) or No)

() PIPELINE RETIREMENT MAIN () SERVICE ()

TYPE OF PIPE: _____

SIZE OF PIPE: _____

LENGTH OF LINE: _____

REASON FOR RETIREMENT: _____

WAS LINE PURGED WITH AIR? Y / N % NG _____

(X) NEW PIPELINE INSTALLATION MAIN () SERVICE (X)

TYPE OF PIPE: HDPE SDR 11

SIZE OF PIPE: 1"

LENGTH OF LINE: 1000 ft.

CUSTOMER NAME IF SERVICE LINE: Brent Hamilton

WAS LINE PURGED WITH NATURAL GAS? (Y) / N % NG 100

() PIPELINE REPLACEMENT MAIN () SERVICE ()

TYPE OF EXISTING PIPE: _____

SIZE OF EXISTING PIPE: _____

TYPE OF NEW PIPE: _____

SIZE OF NEW PIPE: _____

LENGTH OF LINE BEING REPLACED: _____

WAS OLD LINE PURGED WITH AIR? Y / N % NG _____

WAS NEW LINE PURGED WITH NATURAL GAS? Y / N % NG _____

PIPE CONDITION REPORT

INTERNAL CORROSION: Y / N SEVERITY: _____

EXTERNAL CORROSION: Y / N SEVERITY: _____

SIGNATURE: Ruth Gable

1/2/2020

DATE: 4-23-24

FORM 4

NAVITAS UTILITY CORPORATION 2024

RISER PRESSURE TEST

Riser number 0002 Pipe size 1" Location of test FieldRiser information: 1" IPS Central Plastics AnodlessRiser.Gauge number 69411 Test with Air Start time 12:03 End time 1:03 Temp. _____Start pressure 60psig End pressure 60psig Date 4-23-24 Signature Nathan KuleLocation set 320 Co. Rd. 1100Date set 4-23-24 Signature Nathan Kule

Riser number _____ Pipe size _____ Location of test _____

Riser information: _____

Gauge number _____ Test with _____ Start time _____ End time _____ Temp. _____

Start pressure _____ End pressure _____ Date _____ Signature _____

Location set _____

Date set _____ Signature _____

Riser number _____ Pipe size _____ Location of test _____

Riser information: _____

Gauge number _____ Test with _____ Start time _____ End time _____ Temp. _____

Start pressure _____ End pressure _____ Date _____ Signature _____

Location set _____

Date set _____ Signature _____

NAVITAS UTILITY CORPORATION 2024
EFV PRESSURE TEST

EFV number 527 Pipe size 1" Location of test Field

EFV information: HDPE Lyco EFV I Series 475

Gauge number 69411 Test with Air Start time 11:03 End time 11:05 Temp. _____

Start pressure 5psig End pressure 5psig Date 4-23-24 Signature Patth Halele

Location set 320 Co Rd. 1100 East Point KY @ Tap

Date set 4-23-24 Signature Patth Halele

EFV number _____ Pipe size _____ Location of test _____

EFV information: _____

Gauge number _____ Test with _____ Start time _____ End time _____ Temp. _____

Start pressure _____ End pressure _____ Date _____ Signature _____

Location set _____

Date set _____ Signature _____

EFV number _____ Pipe size _____ Location of test _____

EFV information: _____

Gauge number _____ Test with _____ Start time _____ End time _____ Temp. _____

Start pressure _____ End pressure _____ Date _____ Signature _____

Location set _____

Date set _____ Signature _____

[illegible]

PIPELINE FIELD TEST REPORT 2024

NAVITAS UTILITY CORP.

SYSTEM: Navitas Utility

This form must be completed for each section of newly installed section of main or service line.

TEST DATA

Location of line: 24 & 23 Groble Ln. Van Lear KY.

Pipe information: HDPE SDR 11 - Tested roll @ 60 psig for 1 hour.

Size of pipe: 1 inches. Length of line: ~~300~~ 300 ft. Main ☒ Service ()

Pipe information: HDPE SDR 11 - Tested roll @ 60 psig for 1 hour.

Size of pipe: 1 inches. Length of line: ~~100~~ 100 ft. Main () Service ☒

Pipe information: HDPE SDR 11 - Tested roll @ 60 psig for 1 hour.

Size of pipe: 1 inches. Length of line: 100 ft. Main () Service ☒

Pipe information: _____

Size of pipe: _____ inches. Length of line: _____ Main () Service ()

Tested with: Air ☒ Natural Gas () Gauge #: 69411

Time started: 3:10 a.m./p.m. Time ended: 4:10 a.m./p.m.

Test pressure start: 60 psig

Test pressure stop: 60 psig

Line loss: Yes () No ☒

Remarks: _____

Signature: Nath Gable Date: 4-23-24

2024

NUC / FCFA PIPELINE UPDATE WORK SHEET

SYSTEM: Navitas Utility DATE: 4-23-24
 LOCATION: 23 & 24 Groble Ln, Van Lear KY
 GPS COORDINATES: LAT: 37.777039 LON: -82.780883
 Map update (Yes or No)

() PIPELINE RETIREMENT MAIN () SERVICE ()

TYPE OF PIPE: _____

SIZE OF PIPE: _____

LENGTH OF LINE: _____

REASON FOR RETIREMENT: _____

WAS LINE PURGED WITH AIR? Y / N % NG _____

() NEW PIPELINE INSTALLATION MAIN () SERVICE (X)

TYPE OF PIPE: HDPE SDR 11

SIZE OF PIPE: 1"

LENGTH OF LINE: 200 ft.

CUSTOMER NAME IF SERVICE LINE: Cust has not had meter set

WAS LINE PURGED WITH NATURAL GAS? (Y) / N % NG 100

() PIPELINE REPLACEMENT MAIN () SERVICE ()

TYPE OF EXISTING PIPE: _____

SIZE OF EXISTING PIPE: _____

TYPE OF NEW PIPE: _____

SIZE OF NEW PIPE: _____

LENGTH OF LINE BEING REPLACED: _____

WAS OLD LINE PURGED WITH AIR? Y / N % NG _____

WAS NEW LINE PURGED WITH NATURAL GAS? Y / N % NG _____

PIPE CONDITION REPORT

INTERNAL CORROSION: Y / N SEVERITY: _____

EXTERNAL CORROSION: Y / N SEVERITY: _____

SIGNATURE: Patricia Solis

1/2/2020

DATE: 4-23-24

FORM 4

NAVITAS UTILITY CORPORATION 2024
RISER PRESSURE TEST

Riser number 0003 Pipe size 1" Location of test Field

Riser information: 1" IPS Central Plastics Anodless
Riser.

Gauge number 69411 Test with Air Start time 5:00 pm End time 6:00 pm Temp. _____

Start pressure 60 psig End pressure 60 psig Date 4-23-24 Signature Nattho Galile

Location set 23 Groble Ln. Van Lear KY

Date set 4-23-24 Signature Nattho Galile

Riser number 0004 Pipe size 1" Location of test Field

Riser information: 1" IPS Central Plastics Anodless
Riser.

Gauge number 69411 Test with Air Start time 5:00 pm End time 6:00 pm Temp. _____

Start pressure 60 psig End pressure 60 psig Date 4-23-24 Signature Nattho Galile

Location set 24 Groble Ln, Van Lear KY.

Date set 4-23-24 Signature Nattho Galile

Riser number _____ Pipe size _____ Location of test _____

Riser information: _____

Gauge number _____ Test with _____ Start time _____ End time _____ Temp. _____

Start pressure _____ End pressure _____ Date _____ Signature _____

Location set _____

Date set _____ Signature _____

NAVITAS UTILITY CORPORATION 2024
EFV PRESSURE TEST

EFV number 528 Pipe size 1" Location of test Field

EFV information: HDPE LYCO EFV 1 Series 475

Gauge number 69411 Test with Air Start time 6:00 End time 6:02 Temp. _____

Start pressure 5psig End pressure 5psig Date 4-23-24 Signature Pathe Hehle

Location set 23 Groble Ln, Van Lear KY

Date set 4-23-24 Signature Pathe Hehle

EFV number 530 Pipe size 1" Location of test Field

EFV information: HDPE LYCO EFV 1 Series 475

Gauge number 69411 Test with Air Start time 6:00 End time 6:02 Temp. _____

Start pressure 5psig End pressure 5psig Date 4-23-24 Signature Pathe Hehle

Location set 24 Groble Ln, Van Lear KY

Date set 4-23-24 Signature Pathe Hehle

EFV number _____ Pipe size _____ Location of test _____

EFV information: _____

Gauge number _____ Test with _____ Start time _____ End time _____ Temp. _____

Start pressure _____ End pressure _____ Date _____ Signature _____

Location set _____

Date set _____ Signature _____