

Archived: Thursday, May 31, 2012 3:41:24 PM
From: [Eric M. Robeson](#)
Sent: Monday, August 01, 2011 10:23:00 AM
To: ADAM.C.LANDRY@sargentlundy.com
Subject: more comments on env draft
Response requested: No
Importance: Normal

Regarding Table 2-1a, where did the fuel load heat input come from?

We cannot see where C3 is greater than C1 or C2

Also, C3 gross rating is 165 MW

For NOx control, all 3 units also have OFA

Finally, it is a limestone scrubber at Coleman

Eric