

**RECEIVED**

**DEC 29 2025**

**From:** Paula Ratliff

**Sent:** Monday, December 29, 2025 3:49:22 PM

**To:** Stump, Kenya K (EEC)

**Subject:** Photo for Deputy Lyons

**PUBLIC SERVICE  
COMMISSION**

Hello!

Would you be so kind as to forward this photo to Deputy Lyons. This photo is from Henderson County Solar, developed by Geronimo Power, the same company proposing the project in Green County who testified last week that the panels do not break and if they break, they will store them inside.

In August of this year, this project was vandalized and several panels were damaged with gun fire. This photo was taken Labor Day Weekend.

If you enlarge to the left, you will see huge holes in the panels. Obviously, the glass shards are somewhere. You will also note, these are outside - not inside as Geronimo testified they would do, if a panel is damaged.

I have made contact with the sheriff's department and hope to obtain better photos, but if not, this one proves several points. They break. There are shards. They are not stored inside. Chemicals are leaching.



Thank you. Paula Pedigo