

BTU GAS CO., INC.

P.O. BOX 707
SALYERSVILLE, KY 41465
PHONE: 606-884-2000
FAX: 606-884-2010
E-MAIL: pamwilliams@foothills.net

April 13, 2011


Public Service Commission
211 Sower Blvd.
P.O. Box 615
Frankfort, KY 40602-0615
Attn: Jason Brangers

Dear Mr. Brangers;

Enclosed you will find the odorization reports for January 2011 through April 3, 2011. Heather faxed these to me yesterday and today. BTU Gas hired Frontier Gas to conduct these weekly odorizations for us. This odorization is done weekly but we do not get the reports weekly.

Should you have any questions, please feel free to contact us.

Sincerely,



Pam Williams
President

RECEIVED

APR 13 2011

PUBLIC SERVICE
COMMISSION

DTEX Test Log

Test #	00008	BTU GAS TEST #1	User	JASON WESLEY
Test Start Date	01-06-11	BTU OFFICE GARAGE	Notes:	
Test Start Time	04:33:14	<Blank>	DTEX Model	DX1000G
TDL Result	0.03%	SAI YERSVILLE	Serial Number	40984
RDL Result	0.06%	KY	Test Error Code	**
Test Time (Sec)	11	Altitude (ft): 0	Test Temp (C):	18

DTEX Test Log

Test #	00007	BTU GAS TEST #2	User:	JASON WESLEY
Test Start Date	21-08-11	ELK R	Notes:	
Test Start Time	03:47:14	<Blank>	DTEX Model	DX1000G
TDL Result	0.03%	SALYERSVILLE	Serial Number:	40984
RDL Result	0.67%	KY	Test Error Code	**
Test Time (Sec)	10	Altitude (ft) 0	Test Temp (C):	18

Sent 2/4/11
HP

DTEX Test Log

Test #	00005	BTU GAS TEST #3	User:	JASON WESLEY
Test Start Date	01-06-11	MOUTH OF LITTERAL FK	Notes	
Test Start Time	03:21:24		DTEX Model:	DX1000G
TDL Result	0.03%	SALYERSVILLE	Serial Number	40984
RDL Result:	0.63%	KY	Test Error Code	**
Test Time (Sec)	10	Altitude (ft): 0	Test Temp (C)	18

DTEX Test Log

Test #	00005	BTU GAS TEST #4	User	JASON WESLEY
Test Start Date	01-06-11	RT 114 METER SET	Notes	
Test Start Time	02:55:14	<Blank>	DTEX Model	DX1000G
TDL Result	0.03%	SALYERSVILLE	Serial Number	40984
RDL Result	0.67%	KY	Test Error Code	**
Test Time (Sec)	11	Altitude (ft) 0	Test Temp (C)	18

DTEX Test Log

Test #	00024	BTU GAS TEST #1	User	JASON WESLEY
Test Start Date	01-20-11	BTU OFFICE GARAGE	Notes:	
Test Start Time	05:16:15	<Blank>	DTEX Model	DX1000G
TDL Result	0.03%	SALYERSVILLE	Serial Number	40984
RDL Result	0.67%	KY	Test Error Code	**
Test Time (Sec)	13	Altitude (ft) 0	Test Temp (C)	22

DTEX Test Log

Test #	00023	BTU GAS TEST #2	User:	JASON WESLEY	
Test Start Date	01-20-11	ELK CR	Notes:		
Test Start Time	03:48:16	<Blank>	DTEX Model	DX1000G	
TDL Result	0.03%	SALYERSVILLE	Serial Number	40984	
RDL Result	0.63%	KY	Test Error Code	**	
Test Time (Sec)	32	Altitude (ft): 0	41465	Test Temp (C)	22

Sent 2/4/11
HP

DTEX Test Log

Test #	00022	BTU GAS TEST #3	User:	JASON WESLEY
Test Start Date	01-20-11	MOUTH OF LITTERAL FK	Notes:	
Test Start Time	03:27:15		DTEX Model	UX10003
TDL Result	0.02%	SALYERSVILLE	Serial Number	40984
RDL Result	0.56%	KY	Test Error Code	**
Test Time (Sec)	15	Altitude (ft) 0	Test Temp (C)	24

Test #
Test Start Date
Test Start Time
IDL Result
RDL Result
Test Time (Sec)

11/11/11
10:00:00
10:00:00
10:00:00
10:00:00

BT
METER
10:00:00
10:00:00
10:00:00

10:00:00
10:00:00
10:00:00
10:00:00
10:00:00
10:00:00

DTEX Test Log

Test #	00036	BTU GAS TEST #1	User	JASON WESLEY	
Test Start Date	01-26-11	BTU OFFICE GARAGE	Notes		
Test Start Time	04 11 15	<Blank>	DTEX Model	DX1000G	
TDL Result	0.03%	SALYERSVILLE	Serial Number	40984	
RDL Result	0.71%	KY	Test Error Code	**	
Test Time (Sec)	14	Altitude (ft) 0	41465	Test Temp (C):	17

DTEX Test Log

Test #	00033	BTU GAS TEST #4	User	JASON WESLEY
Test Start Date	01-26-11	KI 114 MEIER SEI	Notes:	
Test Start Time	02:36:29	<?>	DTEX Modr:	DY100DG
TDL Result	0.03%	SALYERSVILLE	Serial Number:	40984
RDL Result	0.67%	KY	Test Error Code	'
Test Time (Sec)	20	Altitude (ft) 0	Test Temp (C):	16

Sent 2/4/11
HP

DTEX Test Log

Test #	00005	BTU GAS TEST #:	User:	JASON WESLEY
Test Start Date	01-26-11	ELK CR	Notes	
Test Start Time	03:35:38	<Blank>	DTEX Model	DX1000G
TDL Result	0.02%	SALYERSVILLE	Serial Number:	40364
RDL Result	0.58%	KY	Test Error Code	**
Test Time (Sec):	14	Altitude (ft): 0	Test Temp (C):	17

DTEX Test Log

Test #.	00034	RTU GAS TEST #3	User	JASON WESLEY
Test Start Date	01-26-11	MOUTH OF LITTERAL L K	Notes	
Test Start Time	03 05:38		DTEX Model	DX1000G
TDL Result	0.02%	SALYEVSMILE	Serial Number	40984
RDL Result	0.63%	KY	Test Error Code	**
Test Time (Sec)	15	Altitude (ft): 0	Test Temp (C)	17

DTEX Test Log

Test #	00003	BTU GAS TEST #4	User	JASON WESLEY	
Test Start Date	02-02-11	RT 114 METER SET	Notes		
Test Start Time	11:52:13	Salisbury	DTEX Model	DX100CG	
TDL Result	0.03%	SALYERSVILLE	Serial Number	40984	
RDL Result	0.64%	KY	Test Error Code	**	
Test Time (Sec)	12	Altitude (ft) 0	41465	Test Temp (C)	21

DTEX Test Log

Test #:	00004	BTU GAS TEST #3	User:	JASON WESLEY
Test Start Date	02-02-11	MOUTH OF LITTERAL FK	Notes	
Test Start Time	12:48:14		DTEX Model:	DX1000G
TDL Result	0.02%	SALYERSVILLE	Serial Number	40984
RDL Result	0.64%	KY	Test Error Code:	**
Test Time (Sec)	11	Altitude (ft): 0	Test Temp (C):	21

DTEX Test Log

Test #	00005	BTU GAS TEST #2	User:	JASON WESLEY	
Test Start Date	02-02-11	ELK CR	Notes:		
Test Start Time	01:27:14	<Blank>	DTEX Model:	DX1000G	
TDL Result	0.02%	SALYERSVILLE	Serial Number:	40964	
RDL Result	0.64%	KY	Test Error Code	-	
Test Time (Sec)	11	Altitude (ft): 0	41465	Test Temp (C)	21

DTEX Test Log

Test #	00007	BTU GAS TEST #1	User	JASON WESLEY
Test Start Date	02-02-11	BTU OFFICE GARAGE	Notes	
Test Start Time	02 23 40	<Blank>	DTEX Model	DX1000G
TDL Result	0.03%	SALYERSVILLE	Serial Number	40984
RDL Result	0.65%	KY	Test Error Code	**
Test Time (Sec)	S	Altitude (ft) 0	Test Temp (C)	21

DTEX Test Log

Test #	00018	BTU GAS TEST #4	User:	JASON WESLEY
Test Start Date	02-09-11	RT 114 METER SET	Notes	
Test Start Time	03:40:13	<Blank>	DTEX Model	DX1000G
TDI Result	0.03%	SALYERSVILLE	Serial Number	40984
RDL Result	0.70%	KY	Test Error Code:	**
Test Time (Sec)	10	Altitude (ft) 0	Test Temp (C)	18

DTEX Test Log

Test #	00019	BTU GAS TEST #3	User	JASON WESLEY
Test Start Date	02-09-11	MOUTH OF LITTERAL FK	Notes	
Test Start Time	04:07:12		DTEX Model	DX1000G
TDL Result	0.04%	SALYERSVILLE	Serial Number	40984
RDL Result	0.65%	KY	Test Error Code	**
Test Time (Sec)	8	Altitude (ft) 0	Test Temp (C)	18

DTEX Test Log

Test #	00020	BTU GAS TEST #2	User:	JASON WESLEY
Test Start Date	02-09-11	ELK CR.	Notes,	
Test Start Time	04:38:12	<Blank>	DTEX Model	DX1000G
TDL Result	0.03%	SALYERSVILLE	Serial Number	40984
RDL Result	0.64%	KY	Test Error Code	--
Test Time (Sec)	18	Altitude (ft) 0	Test Temp (C)	18

DTEX Test Log

Test #	00021	BTU GAS TEST #1	User	JASON WESLEY
Test Start Date:	02-09-11	BTU OFFICE GARAGE	Notes	
Test Start Time	05 21 13	<Blank>	DTEX Model:	DX1000G
TDL Result	0.02%	SALYERSVILLE	Serial Number	40984
RDL Result	0.58%	KY	Test Error Code	**
Test Time (Sec)	8	Altitude (ft) 0	Test Temp (C)	18

DTEX Test Log

Test #	00030	BTU GAS TEST #4	User:	JASON WESLEY	
Test Start Date	02-15-11	RT 114 METER SET	Notes		
Test Start Time	03 32 14	<Blank>	DTEX Model:	DX1000G	
TDL Result	0.01%	SALYERSVILLE	Serial Number:	40984	
RDL Result	0.68%	KY	Test Error Code	**	
Test Time (Sec)	302	Altitude (ft): 0	41465	Test Temp (C)	26

DTEX Test Log

Test #	00001	BTU GAS TEST #3	User:	JASON WESLEY
Test Start Date	02-15-11	MOUTH OF LITTERAL FK	Notes	
Test Start Time	04:06:14		DTEX Model	DX1000G
TDL Result	0.02%	SALYERSVILLE	Serial Number	40984
RDI Result	0.65%	KY	Test Error Code:	**
Test Time (Sec)	12	Altitude (ft): 0	Test Temp (C):	26

DTEX Test Log

Test #:	00032	BTU GAS TEST #2	User:	JASON WESLEY	
Test Start Date	02-15-11	ELK CR	Notes:		
Test Start Time	04:41:13	<Blank>	DTEX Model:	DX1000G	
TDL Result:	0.03%	SALYERSVILLE	Serial Number:	40984	
RDL Result	0.69%	KY	Test Error Code:	--	
Test Time (Sec)	14	Altitude (ft) 0	41465	Test Temp (C):	26

DTEX Test Log

Test #	00033	BTU GAS TEST #1	User:	JASON WESLEY
Test Start Date	02-15-11	BTU OFFICE GARAGE	Notes	
Test Start Time	05:18:12	<Blank>	DTEX Model	DX1000G
TDL Result	0.03%	SALYERSVILLE	Serial Number	40984
RDL Result	0.68%	KY	Test Error Code:	**
Test Time (Sec)	12	Altitude (ft) 0	Test Temp (C)	26

DTEX Test Log

Test #:	00040	BTU GAS TEST #3	User	JASON WESLEY
Test Start Date:	02-22-11	MOUTH OF LITTERAL, FK	Notes:	
Test Start Time:	03:43:12		DTEX Model:	DX1000G
TDL Result:	0.03%	SALYERSVILLE	Serial Number:	40984
RDL Result:	0.62%	KY 41465	Test Error Code:	"
Test Time (Sec):	7	Altitude (ft): 0	Test Temp (C):	28

DTEX Test Log

Test #	00039	BTU GAS TEST #4	User	JASON WESLEY
Test Start Date	02-22-11	RT 114 METER SET	Notes:	
Test Start Time	03 05 13	<Blank>	DTEX Model	DX1000G
TDI Result	0.03%	SALYERSVILLE	Serial Number	40984
RDL Result	0.63%	KY	Test Error Code:	**
Test Time (Sec)	10	Altitude (ft) 0	Test Temp (C)	28

DTEX Test Log

Test #	00040	BTU GAS TEST #3	User	JASON WESLEY
Test Start Date	02-22-11	MOUTH OF LITTERAL FK	Notes	
Test Start Time	03:43:12		DTEX Model	DX1000G
TDL Result	0.03%	SALYERSVILLE	Serial Number	40964
RDI Result	0.52%	KY	Test Error Code	**
Test Time (Sec)	7	Altitude (ft) 0	Test Temp (C)	28

DTEX Test Log

Test #	00041	BTU GAS TEST #2	User	JASON WESLEY	
Test Start Date	02-22-11	ELK CR	Notes:		
Test Start Time	04 28 13	<Blank>	DTEX Model	DX1000G	
TDL Result	0.03%	SALYERSVILLE	Serial Number	40984	
RDL Result	0.67%	KY	Test Error Code	**	
Test Time (Sec)	8	Altitude (ft) 0	41465	Test Temp (C)	28

DTEX Test Log

Test #	00042	BTU GAS TEST #1	User	JASON WESLEY
Test Start Date	02-22-11	BTU OFFICE GARAGE	Notes:	
Test Start Time	05 12 13	<Blank>	DTEX Model:	DX1000G
TDL Result	0.02%	SALYERSVILLE	Serial Number:	40984
RDL Result	0.64%	KY 41465	Test Error Code	**
Test Time (Sec)	8	Altitude (ft): 0	Test Temp (C)	28

DTEX Test Log

Test #	00050	BTU GAS TEST #4	User	JASON WESLEY
Test Start Date	03-01-11	RT 114 METER SET	Notes	
Test Start Time	03:13:11	<Blank>	DTEX Model	DX1000G
TDL Result	0.02%	SALYERSVILLE	Serial Number	40984
RDL Result	0.70%	KY 41465	Test Error Code	**
Test Time (Sec)	10	Altitude (ft) 0	Test Temp (C)	22

DTEX Test Log

Test #	00052	BTU GAS TEST #3	User	JASON WESLEY
Test Start Date	03-01-11	MOUTH OF LITTERAL FK	Notes	
Test Start Time	03:49:36		DTEX Model	DX1000G
TDL Result	0.02%	SALYERSVILLE	Serial Number	40984
RDL Result	0.88%	KY	Test Error Code	**
Test Time (Sec)	10	Altitude (ft) 0	Test Temp (C)	22

DTEX Test Log

Test #	00054	BTU GAS TEST #2	User	JASON WESLEY	
Test Start Date	03-01-11	ELK CR	Notes		
Test Start Time	04 27 46	<Blank>	DTEX Model	DX1000G	
TDL Result	0.02%	SALYERSVILLE	Serial Number	40984	
RDL Result	0.68%	KY	Test Error Code	**	
Test Time (Sec)	9	Altitude (ft) 0	41465	Test Temp (C)	22

DTEX Test Log

Test #	00057	BTU GAS TEST #1	User	JASON WESLEY
Test Start Date	03-01-11	BTU OFFICE GARAGE	Notes	
Test Start Time	05 20 07	<Blank>	DTEX Model	DX1000G
TDL Result	0.05%	SALYERSVILLE	Serial Number	40984
RDL Result	0.66%	KY	Test Error Code	--
Test Time (Sec)	9	Altitude (ft) 0	Test Temp (C)	22

DTEX Test Log

Test #	00010	BTU GAS TEST #3	User	JASON WESLEY
Test Start Date:	03-08-11	MOUTH OF LITTERAL FK	Notes	
Test Start Time:	02:17:18		DTEX Model	DX1000G
TDL Result	0.02%	SALYERSVILLE	Serial Number:	40084
RDL Result	0.61%	KY	Test Error Code	--
Test Time (Sec)	15	Altitude (ft): 0	Test Temp (C):	21

DTEX Test Log

Test #	00012	BTU GAS TEST #2	User:	JASON WESLEY
Test Start Date	03-08-11	ELK CR	Notes:	
Test Start Time	03:21:44	<Blank>	DTEX Model:	DX1000G
TDL Result:	0.03%	SALYERSVILLE	Serial Number:	40984
RDL Result	0.65%	KY	Test Error Code:	**
Test Time (Sec):	14	Altitude (ft) 0	Test Temp (C)	20

DTEX Test Log

Test #	00013	BTU GAS TEST #1	User:	JASON WESLEY
Test Start Date	03-08-11	BTU OFFICE GARAGE	Notes	
Test Start Time	04:37:13	<<Blank>	DTEX Model	DX1000G
TDL Result	0.02%	SALYERSVILLE	Serial Number	40984
RDL Result	0.67%	KY	Test Error Code	--
Test Time (Sec)	26	Altitude (ft): 0	Test Temp (C)	21

DTEX Test Log

Test #	00015	BTU GAS TEST #4	User	JASON WESLEY
Test Start Date	03-08-11	RT 114 METER SET	Notes:	
Test Start Time	05 16 38	<Blank>	DTEX Model	DX1000G
TDL Result	0.02%	SALYERSVILLE	Serial Number	40984
RDL Result	0.65%	KY 41465	Test Error Code	--
Test Time (Sec)	11	Altitude (ft) 0	Test Temp (C)	22

DTEX Test Log

Test #	00025	BTU GAS TEST #4	User	JASON WESLEY
Test Start Date	03-14-11	RT 114 METER SET	Notes:	
Test Start Time	02:38:41	<Blank>	DTEX Model	DX1000G
IDL Result	0.02%	SALYERSVILLE	Serial Number	40984
RDL Result	0.68%	KY	Test Error Code	--
Test Time (Sec)	12	Altitude (ft) 0	Test Temp (C)	28

DTEX Test Log

Test #	00028	BTU GAS TEST #3	User:	JASON WESLEY
Test Start Date	03-14-11	MOUTH OF LITTERAL FK	Notes:	
Test Start Time	03:13:15		DTEX Model:	DX1000G
TDL Result	0.02%	SALYERSVILLE	Serial Number:	40984
RDL Result	0.56%	KY	Test Error Code:	--
Test Time (Sec)	11	Altitude (ft) 0	Test Temp (C)	28

DTEX Test Log

Test #:	00029	BTU GAS TEST #2	User:	JASON WESLEY
Test Start Date:	03-14-11	ELK CR	Notes:	
Test Start Time:	04:23:12	<Blank>	DTEX Model:	DX1000G
TDI Result:	0.02%	SALYERSVILLE	Serial Number:	40984
RDL Result:	0.66%	KY	Test Error Code:	**
Test Time (Sec):	12	Altitude (ft): 0	Test Temp (C):	28

DTEX Test Log

Test #	00030	BTU GAS TEST #1	User	JASON WESLEY
Test Start Date	03-14-11	BTU OFFICE GARAGE	Notes:	
Test Start Time	05:17:11	<Blank>	DTEX Model:	DX1000G
TDL Result	0.03%	SALYERSVILLE	Serial Number:	40984
RDL Result	0.63%	KY 41465	Test Error Code	**
Test Time (Sec)	12	Altitude (ft): 0	Test Temp (C)	28

DTEX Test Log

Test #	00040	BTU GAS TEST #4	User:	JASON WESLEY
Test Start Date	03-21-11	RT 114 METER SET	Notes	
Test Start Time	02:41:11	<Blank>	DTEX Model	DX1000G
TDL Result	0.02%	SALYERSVILLE	Serial Number	40984
RDL Result	0.56%	KY	Test Error Code	-
Test Time (Sec)	11	Altitude (ft) 0	Test Temp (C)	24

DTEX Test Log

Test #:	00042	BTU GAS TEST #3	User	JASON WESLEY
Test Start Date	03-21-11	MOUTH OF LITTERAL FK	Notes	
Test Start Time	03:13:12		DTEX Model	DX1000G
TDL Result	0.02%	SALYERSVILLE	Serial Number	40984
RDL Result	0.59%	KY	Test Error Code	**
Test Time (Sec)	12	Altitude (ft) 0	Test Temp (C)	24

DTEX Test Log

Test #	00044	BTU GAS TEST #2	User	JASON WESLEY
Test Start Date	03-21-11	ELK CR	Notes	
Test Start Time	04:17:45	<Blank>	DTEX Model	DX1000G
TDL Result	0.03%	SALYERSVILLE	Serial Number:	40984
RDL Result	0.65%	KY	Test Error Code	--
Test Time (Sec)	17	Altitude (ft) 0	Test Temp (C)	24

DTEX Test Log

Test #	00045	BTU GAS TEST #1	User	JASON WESLEY
Test Start Date	03-21-11	BTU OFFICE GARAGE	Notes	
Test Start Time	05 06 13	<Blank>	DTEX Model	DX1000G
TDL Result	0.03%	SALYERSVILLE	Serial Number:	40984
RDL Result	0.64%	KY	Test Error Code:	**
Test Time (Sec)	15	Altitude (ft) 0	Test Temp (C)	24

DTEX Test Log

Test #:	00054	BTU GAS TEST #4	User:	JASON WESLEY	
Test Start Date	03-27-11	RI 114 METER SET	Notes		
Test Start Time	03:07:13	<Blank>	DTEX Model	DX1000G	
TDL Result	0.03%	SALYERSVILLE	Serial Number:	40984	
RDL Result	0.69%	KY	Test Error Code	-	
Test Time (Sec)	15	Altitude (ft): 0	41465	Test Temp (C)	25

DTEX Test Log

Test #	00055	BTU GAS TEST #0	User	JASON WESLEY
Test Start Date	03-27-11	MOUTH OF LITTERAL FK	Notes	
Test Start Time	03:52:16		DTEX Model	DX1000G
TDL Result	0.03%	SALYERSVILLE	Serial Number	40984
RDL Result	0.68%	KY	Test Error Code	**
Test Time (Sec)	14	Altitude (ft) 0	Test Temp (C)	25

DTEX Test Log

Test #	00057	BTU GAS TEST #2	User	JASON WESLEY
Test Start Date:	03-27-11	ELK CR	Notes:	
Test Start Time	04 26 44	<Blank>	DTEX Model	DX1000G
TDL Result	0.03%	SALYERSVILLE	Serial Number	40984
RDL Result	0.64%	KY	Test Error Code	--
Test Time (Sec)	13	Altitude (ft) 0	Test Temp (C)	25

DTEX Test Log

Test #	00059	BTU GAS TEST #1	User	JASON WESLEY
Test Start Date	03-27-11	BTU OFFICE GARAGE	Notes	
Test Start Time	05:19:44	<Blank>	DTEX Model	DX1000G
TDL Result	0.02%	SALYERSVILLE	Serial Number	40984
RDL Result	0.65%	KY	Test Error Code	**
Test Time (Sec)	14	Altitude (ft): 0	Test Temp (C)	24

DTEX Test Log

Test #	00066	BTU GAS TEST #4	User:	JASON WESLEY
Test Start Date	04-03-11	RT. 114 METER SET	Notes:	
Test Start Time	03:39:13	<Blank>	DTEX Model:	DX1000G
TDL Result	0.02%	SALYERSVILLE	Serial Number	40984
RDL Result	0.68%	KY	Test Error Code:	**
Test Time (Sec)	12	Altitude (ft): 0	Test Temp (C):	30

DTEX Test Log

Test #	00067	BTU GAS TEST #3	User	JASON WESLEY
Test Start Date	04-03-11	MOUTH OF LITTERAL FK	Notes	
Test Start Time	04:04:11		DTEX Model	DX1000G
TDL Result	0.03%	SALYERSVILLE	Serial Number	40984
RDL Result	0.67%	KY	Test Error Code:	--
Test Time (Sec)	13	Altitude (ft) 0	Test Temp (C)	30

DTEX Test Log

Test #	00068	BTU GAS TEST #2	User	JASON WESLEY
Test Start Date	04-03-11	ELK CR	Notes	
Test Start Time	04 40 11	<Blank>	DTEX Model	DX1000G
TDL Result	0.03%	SALYERSVILLE	Serial Number	40984
RDI Result	0.69%	KY	Test Error Code	**
Test Time (Sec)	14	Altitude (ft): 0	Test Temp (C):	30

DTEX Test Log

Test #	00069	BTU GAS TEST #1	User	JASON WESLEY
Test Start Date:	04-03-11	BTU OFFICE GARAGE	Notes	
Test Start Time	05:13:14	<Blank>	DTEX Model	DX1000G
TDL Result	0.03%	SALYERSVILLE	Serial Number	40984
RDL Result	0.65%	KY	Test Error Code	**
Test Time (Sec)	14	Altitude (ft): 0	Test Temp (C)	30