

VALVE COMPLIANCE INSPECTION

Location	Size	Lube	Operate	Condition	ID	Date	Location	Size	Lube	Operate	Condition	ID	Date
				Good/PE			Lyon Lumber	4"	✓	✓	Good/Stl		11-8-12
							Lake + 5th	2"	✓		Cast work		11-8-12
							6th + Emberton	2"	✓	✓	Good/Stl		11-8-12
							6th + Lake	2"	✓	✓	Good/Stl		11-8-12
							4th + 5th	3"	✓	✓	Good/Stl		11-8-12
							7th + Columbia	2"	✓	✓	Good/Stl		11-8-12
							Columbia North	2"	✓		Cast work		11-8-12
							Columbia South	3"	✓				11-8-12
							Jackson St. North	2"	✓	✓	Good/Stl		11-8-12
							Jackson St. South	3"	✓	✓	Good/Stl		11-8-12
							Jackson St. Valve	2"	✓	✓	Good/Stl		11-8-12
							2nd + Jackson St.	2"	✓	✓	Good/Stl		11-8-12
							2nd + Magnolia East	2"			Cast work		11-8-12
							2nd + Magnolia South	3"	✓		Broke		11-8-12

Remarks:

Inspected for Compliance

Date

11-8-12