

PATROLLING DISTRIBUTION SYSTEM			
Patrol Starting Date	12-7-12	Patrol Ending Date	
Mapping Section		Block Map Section	

VISUAL OBSERVATION INSPECTION	
Leakage Indicated (location and indication: vegetation, asphalt, concrete, excavation, erosion, tampering, damage)	

Condition at highway, major thoroughfare, secondary road, railroad crossings, right-of-ways.	
--	--

Old Mulkey Rd Creek Crossing - Casing exposed in creek but still solid & holding - / North Magnolia "Town Creek" - Casing is rusted out in a 1ft section pipe is not damaged + coating is ok need to repair.

Other extenuating circumstances that may affect the present and continued safety and integrity of the pipeline facility.	
--	--

Excavation at corner of N. Magnolia + Ky Ave. Pipe has been lowered for excavation.

Follow-up maintenances, repairs, preventative measures, testing, and precautionary actions.	
---	--


Atmospheric corrosion survey, involving localized and general corrosion. Corrosion at the riser where it exits the ground. Checks for the effects of lightening and stray current as well chemical/bacteria electrolytes.	
---	--


Number of qualified employees patrolling ? (1-10)	1
---	---

Signature Patrolling Personnel	<i>Juan Danner</i>	Date of This Report	12-7-12
Signature Patrolling Personnel		Date of This Report	
Signature Patrolling Personnel		Date of This Report	
Signature Patrolling Personnel		Date of This Report	